

Message

---

**From:** Lisa Rector [lrector@nescaum.org]  
**Sent:** 11/20/2020 8:10:20 PM  
**To:** Johnson, Steffan [johnson.steffan@epa.gov]  
**Subject:** FYI on AK summaries

Stef, I thought you should know that the summaries currently posted are missing elements that will be added in the December posting. The additional items will include discrepancies in firebox volumes from test report vs manufacturer materials, owner's manual instructions contradict test method operations, and other major discrepancies between test report and manufacturer materials. Take home, it only gets worse.



**Lisa Rector**, Policy and Program Director at **NESCAUM**

89 South Street, Suite 602, Boston, Massachusetts, 02111 | 802.899.5306 | 617.259.2095 | Fax: 617.742.9162  
| [lrector@nescaum.org](mailto:lrector@nescaum.org)